


- LEGEND**
- AMW-4 PRE-RI MONITORING WELL
 - WMW-1A MONITORING WELL OR CLUSTER INSTALLED IN 1993
 - WMW-3A REPLACEMENT REPLACEMENT MONITORING WELL INSTALLED IN 1996
 - WB-1 BORING INSTALLED IN 1993
 - GEO-1 GEOTECHNICAL BORING INSTALLED IN 1993
 - P-20 PIEZOMETER, INSTALLED IN 1993
 - DCD-SW SURFACE WATER SAMPLE, 1993 INVESTIGATION
 - RG-1 RIVER GAUGE STATION INSTALLED IN 1993
 - WB-5 AIR SAMPLER INSTALLED IN 1993
 - 780 ELEVATION CONTOUR (NGVD 1929)
 - EDGE OF WATER OR DRAINAGE CHANNEL
 - UNPAVED ROAD/TRAIL
 - KPT-5 SEQUENT PROBING TRANSECT



- NOTES:**
- UNLESS OTHERWISE INDICATED ALL SAMPLE LOCATIONS SURVEYED BY WADE-TRIM INC. OCTOBER 1993 THROUGH AUGUST 1996. SAMPLES ARN-1 THROUGH ARN-5 AND WRN-1 THROUGH WRN-5 WERE SURVEYED BY BBL JULY 1993.
 - TOPOGRAPHIC MAPPING PRODUCED USING PHOTOGRAMMETRIC METHODS BY LOCKWOOD, INC. FROM AERIAL PHOTOGRAPHY FLOWN APRIL 1991. KALAMAZOO RIVER SOUTH BANK, EAST OF DAVIS CREEK REVISED PER CURRENT CONDITIONS. ADDITIONAL TOPOGRAPHIC CHANGES AFTER APRIL 1991 ARE NOT SHOWN.
 - ALL LOCATIONS ARE APPROXIMATE.

DRAFT

KALAMAZOO RIVER STUDY GROUP
ALLIED PAPER, INC./PORTAGE CREEK/KALAMAZOO RIVER SUPERFUND SITE
REMEDIAL INVESTIGATION/FOCUSED FEASIBILITY STUDY
WILLOW BOULEVARD/A-SITE OU

**SAMPLE LOCATIONS
(PRE-RI TO 1996)**

BBL BLASLAND, BOUCK & LEE, INC.
engineers & scientists

FIGURE
4

* 64582X02
* QTY=1, WBL, REF
* FIG-2-3
2/22/01 SYR-S4-RLP HSB DJP
64581500/64581601.DWG